



GRAYMONT

JOB POSTING

STATIONARY CLASS "A" TECH

COMPANY	GRAYMONT (PA), INC.	LOCATION:	Pleasant Gap, PA
START DATE	ASAP		

COMMENTS ON IMMIGRATION: If you are applying for a position in another country, please note that the position and your application will have to be considered from an immigration perspective.

DUTIES AND RESPONSIBILITIES:

- Job applicants must pass a comprehensive written, and specific questioning process.
- Must become familiar with all types of equipment and locations at Graymont Inc. (Pleasant Gap/Bellefonte plants) within six (6) months.
- Must be skilled in the machinist field to ensure quality control of manufactured/machined parts supplied by outside vendors.
- Demonstrate proper use of all forms of the machinist tools. i.e. Calipers, micrometers, telescoping gages, and thread pitch gauges etc..
- Chase threads, and use tap and die sets efficiently
Perform all forms of skilled bench work to perform rebuilds as per OEM specifications.
- Repair/rebuild gears sets and reducers to OEM specifications.
- Perform complete trouble shooting of failed equipment, and propose redesign solutions for continued nuance maintenance repair; installation and repair of equipment in field or shop, utilizing the necessary tooling to repair/rebuild to OEM specifications.
- Ability to coordinate the project/to perform the necessary tasks.
- Start and safety operate required plant mobile equipment as necessary
- Perform all functions of a PM program as described by foremen.
- Be capable of using acetylene and Plasma cutting equipment proficiently.
- Observe all safety rules and regulations, good housekeeping and clean-up procedures must be followed on all jobs.
- Prompt reporting to the supervisor.

QUALIFICATIONS:

- A two year higher education/technical degree, or equivalent experience.
- Fulfill all "B" Grade requirements.
- Able to climb steps, ladders and work from high elevations, including man lifts.
- Possess American Welding Certified (AWC) certification.
- Applicant must have and maintain in effect a current Pennsylvania driver's license
- Have all necessary skills to work on pumps, gear reducers, elevators, air compressors, conveyor belts, screws, classifiers, screens, crushers, and all other related plant equipment.



GRAYMONT

- Possess the necessary hand tools (1 ¼ and below) to perform stationary maintenance jobs. Larger tools to be provided by Graymont.
- Be capable of reading and understanding CAD drawings, blue prints, technical articles, and all maintenance manuals required to perform the necessary repairs.
- Must be able to develop “as-built” drawings.
- Must be able to read and write legibly.
- Must be able to be trained and utilize computer related software related to the maintenance functions.
- Be capable of interpreting lube charts and preventive maintenance instructions to properly lubricate equipment.
- Must observe all equipment operator and maintenance safety rules.
- Be capable of performing work with minimum supervision.
- Be capable of operating up to and including 15-ton hydraulic crane safely and efficiently within six (6) months.

Please forward resumes to jking@graymont.com